

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: CORYDON, TOWN OF

Community No: 180086

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	99-05-6142A	10/01/1999	729 NORTH CAPITAL AVENUE	1800860005B	18061C0209C
LOMA	03-05-3472A	06/06/2003	SECTION 30, T3S, R4E ; 1 CEDAR GLADE	1800860005B	18061C0209C 18061C0228C
LOMA	03-05-3678A	07/18/2003	CEDAR GLADE ADDITION, PART OF LOTS 7-10; 753 NORTH CAPITOL AVENUE	1800860005B	18061C0209C
LOMA	07-05-2489A	03/08/2007	764 NORTH CAPITOL AVENUE -- PORTION OF SECTION 30, T3S, R4E (IN)	1800860005B	18061C0209C
LOMA	10-05-4201A	08/24/2010	A PORTION OF LOT 3, AETNA'S LIFE INSURANCE COMPANY ADDITION -- 340 SOUTH CAPITOL AVENUE	1800860005B	18061C0209C
LOMA	11-05-0024A	10/28/2010	LOT 3, SUBDIVISION OF OUT LOT 3 -- 514 EAST CHESTNUT STREET	1800860005B	18061C0228C

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: CORYDON, TOWN OF

Community No: 180086

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	95-05-2036A	09/21/1995	129 S. CAPITOL AVENUE	1800860005B	18061C0209C